

Motorola

AUTO RADIO

S E R V I C E M A N U A L

GENERAL INFORMATION

This model is the same as model NH4AC, except for a few mechanical and electrical parts as indicated below. Refer to the NH4AC Service Manual for service information.

REPLACEMENT PARTS LIST

NOTE: When ordering parts, specify model number of set in addition to part number and description of part.

Same as NH4AC except:

Ref. No.	Part Number	Description	List Price	Part Number	Description	List Price
ELECTRICAL PARTS						
C-8	21K580276	Cap, ceramic tubular: 220 mmf 500V NTC 150 PPM.....	.55	*3A534019 *7B531083	Bolt, tee (spkr mtg)..... Bracket, dial background.....	.05 .45
C-9	*21R120451	Cap, ceramic tubular: 47 mmf 500V NTC 750 PPM.....	.35	*7A534298 *2A534247	Bracket, mtg (on back of receiver) Clip Nut (on mtg brackets).....	.10 .10
C-11	8K122076	Cap, paper tubular: .5 mf 100V.....	.35	*42A534040 8A534163	Clip, speed (spkr mtg)..... Capacitor, ignition coil.....	.05 .85
C-14	8K122076	Cap, paper tubular: .5 mf 100V.....	.35	1V512939 *7B531084	Kit, mounting (incls knobs)..... Plate, dial background retaining..	2.65 .30
MECHANICAL PARTS						

PRICES SUBJECT TO CHANGE WITHOUT NOTICE
*New Item, Appears in any List for First Time

